


The manufacturer may use the mark:



Revision 2.2 October 28, 2022 Surveillance Audit Due November 1, 2025



COW 1505085 C002

exida hereby confirms that the:

Series ML/Series MS Hydraulic Actuators

Cowan Dynamics Inc.

Montreal, QC - Canada

Has been assessed per the relevant requirements of:

IEC 61508: 2010 Parts 1-2

and meets requirements providing a level of integrity to:

Systematic Capability: SC 3 (SIL 3 Capable)

Random Capability: Type A, Route 2_H Device

PFH/PFD_{avg} and Architecture Constraints must be verified for each application

Safety Function:

The actuators will move to the designed safe position per the actuator design within the specified safety time.

Application Restrictions:

The unit must be properly designed into a Safety Instrumented Function per the Safety Manual requirements.





Evaluating Assessor

Certifying Assessor

Certificate / Certificat / Zertifikat / 合格証 COW 1505085 C002

Systematic Capability: SC 3 (SIL 3 Capable)

Random Capability: Type A, Route 2_H Device

PFH/PFD_{avg} and Architecture Constraints must be verified for each application

Systematic Capability:

The product has met manufacturer design process requirements of Safety Integrity Level (SIL) 3. These are intended to achieve sufficient integrity against systematic errors of design by the manufacturer.

A Safety Instrumented Function (SIF) designed with this product must not be used at a SIL level higher than stated.

Random Capability:

The SIL limit imposed by the Architectural Constraints must be met for each element. This device meets exida criteria for Route 2_H .

IEC 61508 Failure Rates in FIT¹, Clean Service

Device	λ _{SD}	λ _{su}	$\lambda_{ extsf{DD}}$	$\lambda_{ extsf{DU}}$
Dual Acting	0	68	0	282
Spring Return	0	269	0	257
Dual Acting with PVST	68	0	160	122
Spring Return with PVST	269	0	142	115

¹ FIT = 1 failure / 10⁹ hours

Note: An automatic PVST must be implemented to use the PVST numbers

SIL Verification:

The Safety Integrity Level (SIL) of an entire Safety Instrumented Function (SIF) must be verified via a calculation of PFH/PFD_{avg} considering redundant architectures, proof test interval, proof test effectiveness, any automatic diagnostics, average repair time and the specific failure rates of all products included in the SIF. Each element must be checked to assure compliance with minimum hardware fault tolerance (HFT) requirements.

The following documents are a mandatory part of certification:

Assessment Report: COW 15-05-085 R004 V1 R4 (or later)

Safety Manual: SIL Safety Guide-Series ML, SIL Safety Guide-Series MS (or later)

Series ML / Series MS Hydraulic Actuators



80 N Main St Sellersville, PA 18960

² PVST = Partial Valve Stroke Test of a final element Device